

网上公开安全评价报告信息公开表

存档编号	LD2025AX0023		
项目名称	阜新蒙古族自治县海洋加油站经营危险化学品安全评价		
评价类型	<input type="checkbox"/> 预评价 <input type="checkbox"/> 验收评价 <input checked="" type="checkbox"/> 现状评价 <input type="checkbox"/> 重大危险源评估		
项目所属行业	石油加工业，化学原料、化学品及医药制造业		
项目简介	<p>阜新蒙古族自治县海洋加油站共有 3 个储罐。其中车用乙醇汽油双层储罐 1 座，储量为 30m³；柴油双层储罐 2 座，储量均为 30m³。税控燃油加油机共 4 台，其中车用乙醇汽油加油机 2 台，柴油加油机 2 台。按《汽车加油加气加氢站技术标准》（GB 50156-2021）3.0.9 中规定，柴油罐容积可折半计入油罐总容积，则该站油罐折合后总容积应为 60m³，故该站为三级加油站。</p>		
安全评价项目组长	李东		
项目技术负责人	姓 名	专 业	
	田宏宇	安全	
项目过程控制负责人	王春荣		
评价报告编制人	李东		
评价报告审核人	梁永瑞		
参与评价的安全评价师	姓 名	专业能力	安全评价人员资格证书编号
	李 东	安 全	1500000000200419
	李雪姣	化工工艺	1800000000200366
	李 玲	电 气	1800000000200336
	杨 春	自 动 化	1500000000301261
	毛占娟	化工机械	21230346155
	赵 阳	安 全	1800000000200347
参与评价的注册安全工程师	李东、李玲、赵阳、毛占娟、杨春		
现场勘查人员	李东、赵阳		
现场勘查时间	2025.8.26		

<p>现场勘查主要任务</p>	<p>考察本项目的厂内厂外周边情况 (包括建构筑物、道路、设施等) 及防火间距</p>
<p>现场勘查照片</p>	 <p>The top photograph shows three individuals standing under the canopy of a gas station. The person on the left is wearing a dark blue polo shirt and black pants. The person in the middle is wearing a white t-shirt and grey pants. The person on the right is wearing a blue work uniform. The background shows gas pumps and a white building. The bottom photograph shows the same three individuals standing in front of a building with a glass entrance. The person on the left is wearing a dark blue polo shirt and black pants. The person in the middle is wearing a white t-shirt and grey pants. The person on the right is wearing a blue work uniform. The building has a blue awning over the entrance.</p>
<p>评价报告提交时间</p>	<p>2025.11.20</p>